

HANKUK RELAY CO.,LTD.

Certificate Holder: 8, Gajeong-ro 77beon-gil, Seo-gu,
22837 Incheon
Republic of Korea

Certificate Number: R 50159775

Order Number: 153121353

Relay

Certified Product: Model Designation:
HR-CR3B1xyz

EN 61810-1:2004

Fulfilled Standards: The standard(s) listed here reflect the status at the time of the release of this certificate.
For more standards and/or upgrades please refer to the latest pages of the same certificate no.

Date of Issue: 2009-07-27

TÜV-Mark Approval

Type Approval

The Type Approval mark of TÜV Rheinland is usually awarded for components that are not ready for use and occasionally also for finished products.

The components are by themselves not ready for use, but intended to be incorporated into finished products.

Certificate Type: The tests focus on the safety of each component. The Type Approval is a voluntary test, which helps TÜV Rheinland to confirm that a product meets the relevant safety requirements.

After type examination the manufacture of products, which have received this test mark, is regularly monitored. The certification is valid as long as the test specifications are up to date and the certificate has not been terminated, neither by the customer nor by TÜV Rheinland. The validity of the certificate expires if changes are made to the product.

Certified products may be labelled with a test mark.

More information can be found here.

HANKUK RELAY CO.,LTD.

Certificate Holder: 8, Gajeong-ro 77beon-gil, Seo-gu,
22837 Incheon
Republic of Korea

Certificate Number: R 50159904

Order Number: 153121355

Relay

Certified Product: Model Designation:
HR-CR3B2xy

EN 61810-1:2004

Fulfilled Standards: The standard(s) listed here reflect the status at the time of the release of this certificate.
For more standards and/or upgrades please refer to the latest pages of the same certificate no.

Date of Issue: 2009-07-23

TÜV-Mark Approval

Type Approval

The Type Approval mark of TÜV Rheinland is usually awarded for components that are not ready for use and occasionally also for finished products.

The components are by themselves not ready for use, but intended to be incorporated into finished products.

Certificate Type: The tests focus on the safety of each component. The Type Approval is a voluntary test, which helps TÜV Rheinland to confirm that a product meets the relevant safety requirements.

After type examination the manufacture of products, which have received this test mark, is regularly monitored. The certification is valid as long as the test specifications are up to date and the certificate has not been terminated, neither by the customer nor by TÜV Rheinland. The validity of the certificate expires if changes are made to the product.

Certified products may be labelled with a test mark.

More information can be found here.

CERTIFICATE OF COMPLIANCE

Certificate Number E94269
Report Reference E94269-20000329
Issue Date 2021-JUNE-11

Issued to: HANKUK RELAY CO LTD
152-1 Kajwa-Dong
Seo-Ku
Inchon, 404-250 Republic of Korea

This certificate confirms that representative samples of SWITCHES, INDUSTRIAL CONTROL - COMPONENT
See Addendum Page

Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety: UL 508 and CAN/CSA C22.2 No. 14-18, CAN/CSA C22.2 No. 14-13, CSA C22.2 NO. 14-10 and CAN/CSA C22.2 No. 14-18 - -Standard for Industrial Control Equipment.

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E94269
Report Reference E94269-20000329
Issue Date 2021-JUNE-11

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Relays

HR-CR6 DC05V ,HR-CR6 DC12V ,HR-CR6 DC24V ,HR-CR6P DC05V ,HR-CR6P DC12V ,HR-CR6P DC24V , , ,HR703FDC03V ,HR703FDC05V ,HR703FDC06V ,HR703FDC09V ,HR703FDC12V ,HR703FDC24V ,HR703FDC48V , ,HR702NHDC03V ,HR702NHDC05V ,HR702NHDC06V ,HR702NHDC09V ,HR702NHDC12V ,HR702NHDC24V ,HR702NHDC48V ,HR703HDC03V ,HR703HDC05V ,HR703HDC06V ,HR703HDC09V ,HR703HDC12V ,HR703HDC24V ,HR703HDC48V ,HR91A03 ,HR91A05 ,HR91A06 ,HR91A09 ,HR91A12 ,HR91A24 ,HR91C03 ,HR91C05 ,HR91C06 ,HR91C09 ,HR91C12 ,HR91C24 ,HR96A 03 ,HR96A 05 ,HR96A 06 ,HR96A 09 ,HR96A 12 ,HR96A 18 ,HR96A 24 , , ,HR96C 03 ,HR96C 05 ,HR96C 06 ,HR96C 09 ,HR96C 12 ,HR96C 18 ,HR96C 24 ,HR96A 05H ,HR96A 06H ,HR96A 09H ,HR96A 12H ,HR96A 18H ,HR96A 24H ,HR96C 05H ,HR96C 06H ,HR96C 09H ,HR96C 12H ,HR96C 18H ,HR96C 24H ,HR80A DC03H ,HR80A DC05H ,HR80A DC06H ,HR80A DC09H ,HR80A DC12H ,HR80A DC24H ,HR80A DC48H ,HR-CR3B13DC05 ,HR-CR3B13DC06 ,HR-CR3B13DC09 ,HR-CR3B13DC12 ,HR-CR3B13DC18 ,HR-CR3B13DC24 ,HR-CR3B13DC48 ,HR-CR3B11DC05 , , ,HR-CR3B11DC06 ,HR-CR3B11DC09 ,HR-CR3B11DC12 ,HR-CR3B11DC18 ,HR-CR3B11DC24 ,HR-CR3B11DC48 ,HR-CR3B13DC05K ,HR-CR3B13DC06K ,HR-CR3B13DC09K ,HR-CR3B13DC12K ,HR-CR3B13DC18K ,HR-CR3B13DC24K ,HR-CR3B13DC48K ,HR-CR3B11DC05K ,HR-CR3B11DC06K ,HR-CR3B11DC09K ,HR-CR3B11DC12K ,HR-CR3B11DC18K ,HR-CR3B11DC24K ,HR-CR3B11DC48K ,HR-CR3B23DC05 ,HR-CR3B23DC06 ,HR-CR3B23DC09 ,HR-CR3B23DC12 ,HR-CR3B23DC18 ,HR-CR3B23DC24 ,HR-CR3B23DC48 ,HR-CR3B21DC05 ,HR-CR3B21DC06 ,HR-CR3B21DC09 ,HR-CR3B21DC12 ,HR-CR3B21DC18 ,HR-CR3B21DC24 ,HR-CR3B21DC48 , , ,HR93F DC03 ,HR93F DC05 ,HR93F DC06 ,HR93F DC09 ,HR93F DC12 ,HR93F DC24 ,HR93F DC03H ,HR93F DC05H ,HR93F DC06H ,HR93F DC09H ,HR93F DC12H ,HR93F DC24H ,HR93 DC03 ,HR93 DC05 ,HR93 DC06 ,HR93 DC09 ,HR93 DC12 ,HR93 DC24 ,HR93 DC03H ,HR93 DC05H ,HR93 DC06H ,HR93 DC09H ,HR93 DC12H ,HR93 DC24H , ,HR90 DC03-H ,HR90 DC05-H ,HR90 DC06-H ,HR90 DC09-H ,HR90 DC12-H ,HR90 DC24-H ,HR90 DC48-H , , ,HR90 DC03-U ,HR90 DC05-U ,HR90 DC06-U ,HR90 DC09-U ,HR90 DC12-U ,HR90 DC24-U ,HR90 DC48-U ,HR90 DC03 ,HR90 DC05 ,HR90 DC06 ,HR90 DC09 ,HR90 DC12 ,HR90 DC24 ,HR90 DC48 ,HR90 DC03-V ,HR90 DC05-V ,HR90 DC06-V ,HR90 DC09-V ,HR90 DC12-V ,HR90 DC24-V ,HR90 DC48-V , ,HR-CR7DC03 ,HR-CR7DC05 ,HR-CR7DC06 ,HR-CR7DC09 ,HR-CR7DC12 ,HR-CR7DC24 ,HR-CR7DC48 ,HR-CR3A13DC03 ,HR-CR3A13DC05 , ,HR-CR3A13DC06 ,HR-CR3A13DC09 ,HR-CR3A13DC12 ,HR-CR3A13DC24 ,HR-CR3A13DC48 ,HR-CR3A11DC03 ,HR-CR3A11DC05 ,HR-CR3A11DC06 ,HR-CR3A11DC09 ,HR-CR3A11DC12 ,HR-CR3A11DC24 ,HR-CR3A11DC48 ,HR-CR3A13DC05H ,HR-CR3A13DC06H ,HR-CR3A13DC09H ,HR-CR3A13DC12H ,HR-CR3A13DC24H ,HR-CR3A13DC48H ,HR-CR3A11DC03H ,HR-CR3A11DC05H ,HR-CR3A11DC06H ,HR-CR3A11DC09H ,HR-CR3A11DC12H ,HR-CR3A11DC24H ,HR-CR3A11DC48H , ,HR-CR3A21DC03 ,HR-CR3A21DC05 ,HR-CR3A21DC06 ,HR-CR3A21DC09 ,HR-CR3A21DC12 , , ,HR-CR3A21DC24 ,HR-CR3A21DC48 ,HR-CR3A23DC03 ,HR-CR3A23DC05 ,HR-CR3A23DC06 ,HR-CR3A23DC09 ,HR-CR3A23DC12 ,HR-CR3A23DC24 ,HR-CR3A21DC03H ,HR-CR3A21DC05H ,HR-CR3A21DC06H ,HR-CR3A21DC09H ,HR-

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>




CERTIFICATE OF COMPLIANCE

Certificate Number E94269
Report Reference E94269-20000329
Issue Date 2021-JUNE-11

CR3A21DC12H ,HR-CR3A21DC24H ,HR-CR3A21DC48H ,HR-CR3A23DC03H ,HR-CR3A23DC05H ,HR-CR3A23DC06H ,HR-CR3A23DC09H ,HR-CR3A23DC12H ,HR-CR3A23DC24H ,HR-CR3A23DC48H ,HR-CR3A11DC03K ,HR-CR3A11DC05K ,HR-CR3A11DC06K ,HR-CR3A11DC09K ,HR-CR3A11DC12K ,HR-CR3A11DC24K ,HR-CR3A11DC48K ,HR-CR3A13DC03K ,HR-CR3A13DC05K ,HR-CR3A13DC06K ,HR-CR3A13DC09K , ,HR-CR3A13DC12K ,HR-CR3A13DC24K ,HR-CR3A13DC48K ,HR-CR3A11DC03KH ,HR-CR3A11DC05KH ,HR-CR3A11DC06KH ,HR-CR3A11DC09KH ,HR-CR3A11DC12KH ,HR-CR3A11DC24KH ,HR-CR3A11DC48KH ,HR-CR3A13DC03KH ,HR-CR3A13DC05KH ,HR-CR3A13DC06KH ,HR-CR3A13DC09KH ,HR-CR3A13DC12KH ,HR-CR3A13DC24KH ,HR-CR3A13DC48KH , ,HR702HH DC03V ,HR702HH DC05V ,HR702HH DC06V ,HR702HH DC09V ,HR702HH DC12V ,HR702HH DC24V ,HR702HH DC48V , ,HR80A DC03HT ,HR80A DC05HT ,HR80A DC06HT ,HR80A DC09HT ,HR80A DC12HT ,HR80A DC24HT ,HR80A DC48HT , ,HR85AKSW DC012 ,HR85AKSW DC024 ,HR85AKS DC012 ,HR85AKS DC024 ,HR85CKSW DC012 ,HR85CKSW DC024 ,HR85CKS DC012 ,HR85CKS DC024 .

Industrial Control Switches

HRCR3N23DC03H ,HRCR3N23DC05H ,HRCR3N23DC06H ,HRCR3N23DC09H ,HRCR3N23DC12H , HRCR3N23DC24H ,HRCR3N23DC48H , ,HR92 DC03H ,HR92 DC05H ,HR92 DC06H ,HR92 DC09H ,HR92 DC12H ,HR92 DC24H , ,HR85AKSW DC005 ,HR85AKS DC005 ,HR85CKSW DC005 ,HR85CKS DC005 ,HR85ATSW DC005 ,HR85ATSW DC012 ,HR85ATSW DC024 ,HR85ATS DC005 ,HR85ATS DC012 ,HR85ATS DC024 ,HR85CTSW DC005 ,HR85CTSW DC012 ,HR85CTSW DC024 ,HR85CTS DC005 ,HR85CTS DC012 ,HR85CTS DC024 , .



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

